

21 STATE CIRCLE  
SHAW HOUSE  
ANNAPOLIS, MARYLAND 21401

HISTORIC SITES SURVEY FIELD SHEET  
Individual Structure Survey Form

D-678 D-628  
NEGATIVE FILE NUMBER: 11/29/98

UTM REFERENCES:  
Zone/Easting/Northing

U.S.G.S. QUAD MAP:

PRESENT FORMAL NAME:  
WILLIAM MILLS House

ORIGINAL FORMAL NAME:  
EMMA SMITH House

PRESENT USE:

ORIGINAL USE:

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:  
EMMA + JAMES SMITH

PHYSICAL CONDITION OF STRUCTURE:  
Excellent ( ) Good ( )  
Fair (X) Poor ( )

THEME:

STYLE:

DATE BUILT: 1882

COUNTY: Dorchester

TOWN: East New Market

LOCATION: School Street  
Route 14  
East New Market

COMMON NAME:  
WILLIAM MILLS House

FUNCTIONAL TYPE: dwelling/residential

OWNER: Mr. and Mrs. William B. Mills

ADDRESS: same as above  
(rental property)

ACCESSIBILITY TO PUBLIC:  
Yes (X) No ( ) Restricted ( )

LEVEL OF SIGNIFICANCE:  
Local (X) State ( ) National ( )

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone ( ) Brick (X) Concrete ( ) Concrete Block ( )
2. Wall Structure
  - A. Wood Frame: Post and Beam ( ) Balloon (X)
  - B. Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
  - C. Iron ( ) D. Steel ( ) E. Other:
3. Wall Covering: Clapboard ( ) Board and Batten ( ) Wood Shingle ( ) Shiplap ( )  
Novelty ( ) Stucco ( ) Sheet Metal ( ) Aluminum ( ) Asphalt Shingle ( )  
Brick Veneer ( ) Stone Veneer ( ) ASBESTOS (X)  
bonding Pattern: Other:
4. Roof Structure
  - A. Truss: Wood ( ) Iron ( ) Steel ( ) Concrete ( )
  - B. Other:
5. Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle (X) Sheet Metal ( )  
Built Up ( ) Rolled ( ) Tile ( ) Other:
6. Engineering Structure:
7. Other:

Appendages: Porches ( ) Towers ( ) Cupolas ( ) Dormers ( ) Chimneys ( ) Sheds ( ) Ells (X)  
Wings ( ) Other:

Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( ) With False Front ( )  
Other:

Number of Stories: 2 Story

Number of Bays: 2

Approximate Dimensions: 2 X 2 BAYS

Entrance Location: 1ST BAY

THREAT TO STRUCTURE:

No Threat ( ) Zoning ( ) Roads ( )  
Development ( ) Deterioration ( )  
Alteration (X) Other:

LOCAL ATTITUDES:

Positive (X) Negative ( )  
Mixed ( ) Other:

GENERAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:



D-628

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Lane( ) Woodland( ) Scattered Buildings( )  
Moderately Built Up(x) Densely Built Up( )  
Residential( ) Commercial( )  
Agricultural( ) Industrial( )  
Roadside Strip Development( )  
Other:

RECORDED BY:

East New Market Historic District Commission

ORGANIZATION:

Summer, 1985

DATE RECORDED:

Sara Rossing

PROPERTY OWNED BY MR. AND MRS. WM. MILLS

2-story, L-shaped, gabled asphalt tile roof; 2 inside chimneys. Weatherboard has been covered with asbestos tile. 2 over 2 windows. Front facade is 2 bay; entrance in 2nd. Boxed cornices with returns. Modern porch with wrought iron railings. Enclosed porch in back converted into a 1-story addition.

OUTBUILDING

Vertical board shed--originally a chicken house.


Note: FROM BETWEEN THE NANTICOKE AND THE CHOPTANK

"Emma Smith House, East New Market, 1882, Private

This two-and-one-half-story frame house was built around 1882 by Emma and James Smith and has remained largely unaltered to this day. It, and its neighbor, the Christina Andrew House, are examples of what middle-income farmers and tradespeople were building at the end of the century."

D-628

EAST NEW MARKET QUADRANGLE  
MARYLAND  
7.5 MINUTE SERIES (TOPOGRAPHIC)





D-628

72%

